



# TRMS 1000Aac CLAMP METER

## DCM3000



- Measurements: AC/DC Voltage, AC Current and resistance
- True RMS measurement (TRMS)
- Diode and continuity test
- Non-contact voltage detection
- Automatic range
- 6000 counts
- Max/Min values
- Relative measurement
- Auto-off and low battery indicator
- CAT IV conforms EN 61010





# DCM3000

## TRMS 1000Aac CLAMP METER

General	
Display	6000 counts
Auto power off	✓
Backlight	✓
HOLD	✓
Diode and continuity test	✓
Auto-ranging	✓
MIX/MAX/REL	✓
NCVD	✓
Jaw size	40m
Worklight	✓
Dimensions	130x255x60mm
Weight	765g
Power Supply	LR03, 3x1,5V AAA
Standars	EC 61010-1, IEC/EN61010-2-033
Safety rating	CAT IV 600V, CAT III 1000V
Accesories included	Test leads, user manual, calibration certificate, batteries and bag



Dipl.-Ing. Matthias Schniebel  
Pfarrgasse 1  
01920 Elstra  
Germany

Tel.: +49 (35793) 395190  
Fax: +49 (35793) 395191  
Email: [info@schniebel.com](mailto:info@schniebel.com)  
[www.schniebel.com](http://www.schniebel.com)



# DCM3000

## TRMS 1000Aac CLAMP METER

Specs	
TRMS measurements	✓
DC Voltage(V)	1000V
AC Voltage(V)	750V
AC Current	1000A
Resistance	20MΩ
Diode Test	✓
Continuity Test	✓

Data for ordering	
SKU	KPSDCM3000CBINT
EAN code	8435394777696
UPC code	810053671962
pcs/box	30



Dipl.-Ing. Matthias Schniebel  
Pfarrgasse 1  
01920 Elstra  
Germany

Tel.: +49 (35793) 395190  
Fax: +49 (35793) 395191  
Email: [info@schniebel.com](mailto:info@schniebel.com)  
[www.schniebel.com](http://www.schniebel.com)